

09/977026
1/9
20 FIGS




Fig. 1

09/977026-101201




Fig. 2




Fig. 3




Fig. 4

FIG. 1 is a cross-sectional view of a wellbore 18. The wellbore 18 is lined with a casing 200. The casing 200 is composed of sections 202 and 206. The sections 202 are connected by joints 218. The joints 218 are sealed with seals 214. The casing 200 is surrounded by a cement sheath 228. The wellbore 18 is filled with a fluid 20.

Fig. 5B

09977036 404204




Fig. 6A




Fig. 6B




Fig. 6C




Fig. 6D




Fig. 6E




Fig. 6F




Fig. 6G




Fig. 6H

0997026-404304




Fig. 8




Fig. 7A




Fig. 7B




Fig. 7C




Fig. 7D




Fig. 7E